

**Information Services**

**Technical Information Memorandum**

---

**Subject: Extinguishers with Safety Pin & O.K. Indicator**

**Issue Number: 1**

**Date: November, 2007**

Chubb, Gloria and similar extinguishers fitted with a safety pin and snap-off type O.K. indicator must not also be sealed with a pull-tight seal.

Use of a pull-tight plastic seal or similar will increase the breaking strain necessary to remove the safety pin.

Besides making the extinguisher unacceptably difficult to operate it will invalidate the BS EN3 approval and the manufacturer's warranty.

**BACK**

---

**DISCLAIMER**

The information, facts and opinions expressed in this document are believed to be correct in the light of information available but they are not guaranteed and neither IFEDA or its officers can accept responsibility in respect of these contents or their implementation.

This is an IFEDA member service, which is for the use of IFEDA Full Members only and in this format is copyright of the Independent Fire Engineering & Distributors Association and must not be copied for, or passed to others.