



Information Services

Technical Information Memorandum

From the National Office

Subject	Issue No.	Date
Extinguishers – Wet chemical – Amerex	61	January 2008

Amerex service instructions make it clear that only the specified refill charge should be used to refill.

The extinguisher must be pressurised using nitrogen.

'O' rings should be replaced, using manufacturer's specified product.

The valve stem should also be replaced using manufacturer's specified product, which is part number 14878.

The manufacturer has advised that when test discharge becomes due the contents can be discharged into a suitable clean container and re-used if the discharge test is satisfactory.

There is an environmental advantage if this procedure is adopted.

DISCLAIMER

The information, facts and opinions expressed in this document are believed to be correct in the light of information available, but they are not guaranteed and neither IFEDA nor its Officers can accept any responsibility in respect of these contents or their implementation.

This is an IFEDA member service, which is for the use of IFEDA Full Members only and in this format is copyright © of the Independent Fire Engineering & Distributors Association and must not be copied for, or passed to others.