



Memo-Servicing & Technical Info

I.F.E.D.A. MEMBERS SERVICING/TECHNICAL ADVICE/ UPDATE

From: The National Office


Date: Sept 2008

Number 64

Subject: Thomas Glover, Firepower 6L Foam Extinguishers

Your attention is drawn to the following extinguisher:-

A Firepower 6L Foam Extinguisher, model number FPF6 (9205/00) was produced at our recent committee meeting which had a small hole (a little larger than a pin prick) in the main body caused by corrosion. The effect of this was to cause the lining next to the hole to degrade and the unit to slowly and quietly lose pressure.



DISCLAIMER

The information, facts and opinions expressed in this document are believed to be correct in the light of information currently available, but they are not guaranteed and neither IFEDA nor its officers can accept any responsibility in respect of these contents or their implementation.

This document in its entirety is copyright © of The Independent Fire Engineering & Distributors Association and must not be copied or distributed by any means whatsoever without the prior permission of the Association