



Memo-Servicing & Technical Info

From: The National Office

Date: MAR 2010

Number 75

Basic Service CO2 Extinguishers – BS5306-3 : 2009

Please note, if someone is newly trained (or under guidance) and religiously following every instruction when servicing fire extinguishers please bring to their attention that there is a typo as follows:-

Ref BS5306-3 : 2009 Table D1, page 17 contains an error regarding the basic service of a carbon dioxide extinguisher (there will be an update from BSI in due course).

Please disregard point 6 (six) in the sequence.

DISCLAIMER

The information, facts and opinions expressed in this document are believed to be correct in the light of information currently available, but they are not guaranteed and neither IFEDA nor its officers can accept any responsibility in respect of these contents or their implementation.