

Memo-Servicing & Technical Info

From: The National Office

Date: Feb 2012

Number 79 (previously issued as number 54)

Extinguishers fitted with a safety pin and O.K. indicator

Chubb, Gloria and similar extinguishers fitted with a safety pin and snap-off type O.K. indicator must not also be sealed with a pull-tight (tamper) seal.

Use of a pull-tight plastic seal or similar will increase the breaking strain necessary to remove the safety pin.

Besides making the extinguisher unacceptably difficult to operate it will also invalidate the BS EN3 approval and the manufacturer's warranty.

DISCLAIMER

The information, facts and opinions expressed in this document are believed to be correct in the light of information available but they are not guaranteed. Neither IFEDA nor its officers can accept responsibility in respect of these contents or their implementation.

This is an IFEDA member service, which is for the use of IFEDA Members only and in this format is copyright of the Independent Fire Engineering & Distributors Association. It must not be copied, or passed to others.